



**KOREA OCCUPATIONAL SAFETY & HEALTH AGENCY**

## **INVESTIGATION REPORT**

### **REBOILER HEATER TUBE FIRE**



**Ulsan, Korea**

**October , 2003**

#### **KEY ISSUES:**

- **Tube rupture by high temperature  $H_2S$ -  $H_2$  Corrosion**
- **Reassurance of Convection tube inspection period & inspection method**

## **ABSTRACT**

This report explains the fire that occurred on October, 2003 in a HOU(Heavy Oil Upgrading) Plant, Ulsan, Korea. The fire was arisen due to corrosion of fire heater tube, which was the convection heater tube of pre-fractionator reboiler and released VGO(Vacuum Gas Oil) that ignited. No employee was injured, but potentially polluted material was released into the air. The key safety issues covered in this report were how to inspect the convection heater tube and to select proper tube material of construction at the stage of design. Recommendations concerning this issue were delivered to said Plant.

The Korean Occupational Safety and Health Agency (KOSHA) is a public professional and non-profit organization under the ministry of labor whose mission is to maintain and promote worker's safety and health by efficiently implementing industrial accident prevention projects, and to contribute to the development of the national economy by encouraging employers to adopt accident prevention programs. It is not an enforcement or regulatory body. Established on Dec. 9th, 1987 under the authority of the Korea Occupational Safety and Health Agency Act(enacted May 30th, 1987 under law No. 3931). No part of the conclusions, findings or recommendations of the KOSHA relating to any major industrial accident may be admitted as evidence or used in any action or suit for damages arising out of its actions and decisions through investigation report. The KOSHA makes public its actions and decisions through investigation reports, summary reports, safety studies, safety recommendations, special technical publications, and statistical reviews. More information about the KOSHA may be found on the World Wide Web at <http://www.kosha.net>.

Information about KOSHA publications may be obtained by contacting:

**Korea Occupational Safety and Health Agency**  
**Major Industrial Accident Prevention Department**  
**34-4, Gusan-dong, Bupyeong-gu,**  
**Incheon, 403-711, Korea**  
**Tel: +82-32-5100-500**  
**Fax: +82-32-512-8311**

# **TABLE OF CONTENTS**

## **SUMMARY**

- 1. Introduction**
- 2. Incident**
- 3. Key Findings**
- 4. Root Cause**

## **1.0 INTRODUCTION**

- 1.1 BACKGROUND**
- 1.2 INVESTIGATION PROCESS**

## **2.0 SYSTEM ANALYSIS**

- 2.1 HOU PROCESS**
- 2.2 UC UNIT**

## **3.0 INCIDENT ANALYSIS**

- 3.1 DESCRIPTION**

## **4.0 RESULT OF INVESTIGATION**

- 4.1 Convection Tube Inspection Result**
- 4.2 Convection Tube Scaling Analysis Result**
- 4.3 Vapor/Liquid Pattern and Flow Regime Analysis Result**
- 4.4 Corrosion Mechanism**

## **5.0 ROOT CAUSE**

- 5.1 Tube Rupture by High Temperature H<sub>2</sub>S-H<sub>2</sub> Corrosion**

## **6.0 RECOMMENDATIONS**

- 6.1 Material of Construction of Heater Tube Upgrade**
- 6.2 Reassurance of Convection Tube Inspection Period and Method**

## **7.0 REFERENCE**

## **SUMMARY**

### **1. INTRODUCTION**

On October, 2003, a pre-fractionator reboiler fired in a HOU (Heavy Oil Upgrading) Plant, Ulsan, Korea. The fire continued for 2 hours and damaged reboiler itself. No employees were injured, potentially polluted vent gas was released into the air. Because of the serious nature of the incident, the Korea Occupational Safety and Health Agency initiated an incident investigation. The purpose of the investigation was to identify the root causes of the incident and make recommendations to prevent similar incidents.

The company who owns HOU plant is mainly composed of oil refinery, petrochemical plant, and other facilities for shipping, storing, and so on. It is one of the big refinery and petrochemical complex in the world, with the up-to-date automation process on area of 2000 acres (8.26 million m<sup>2</sup>). There are about 40 plants in the Complex. About 1/3 of them is for petroleum. Another 1/3 is for petrochemical factories. And the last 1/3 is for PE/PP plants, lubricants, and other facilities like a power plant.

### **2. INITIATING EVENT**

The investigation team determined that the fire occurred in the convection section of the reboiler heater. There were no other physical damages except convection part of the heater itself. The investigation team decided to dismantle the heater. 5 days later, the damaged heater was took to pieces. The investigation team found out that the upper side ('E' pass ; the eighth row of convection section in prefractionator reboiler heater) had ruptured and it was split into 2 part with the length of about 2.1m.

### **3. KEY FINDINGS**

The cause of the fire that occurred at the reboiler heater of the UC Unit is high temperature sulfidic corrosion. The report, *Overview of Sulfidic Corrosion in Petroleum Refining* which was proposed by NACE technical committee in 2003, provides the following descriptions of corrosion

- 1) Steel with 5% or even 9% Cr has been observed to corrode at rates as high as CS
- 2) Corrosion can be locally aggressive, such as in areas of higher velocity or turbulent flow, or on the topside of horizontally oriented furnace tubes

3) Corrosion rates can be high, even if total sulfur content is low (several parts per million)

**In this incident, the upper side of the convection had corroded and ruptured so that it caused fire and made damages around the heater and facilities.**

#### **4. Root Cause**

- **Tube rupture by high temperature  $\text{H}_2\text{S}$ -  $\text{H}_2$  Corrosion**

## 1.0 INTRODUCTION



**Figure 1: UC(Unicracking) Unit after fire**

## 1.1 BACKGROUND

On October, 2003, a pre-fractionator reboiler fired in a UC(Unicracking) Unit of HOU (Heavy Oil Upgrading) Plant, Ulsan, Korea. The fire broke out on the eighth row tube on the convection part of the heater. It continued for 2 hours and damaged reboiler itself. No employees were injured. However, potentially polluted vent gas was released into the air. Because of the serious nature of the incident, the Korea Occupational Safety and Health Agency initiated an incident investigation. The purpose of the investigation was to identify the root causes of the incident and make recommendations to prevent similar incidents.

## 1.2 INVESTIGATION PROCESS

The KOSHA investigation team conducted an on-site investigation until November 6, 2003. The scope of the investigation team was to examine and analyze the circumstances of the fire to learn what happened, and to attempt to determine the cause of the fire. The team evaluated the process design and safety management systems to determine their adequacy in controlling the cause of this

fire. The ultimate objective of this investigation was to develop recommendations to help prevent similar incidents.

The team used the following investigation methodology adapted to address overlapping roles and responsibilities of other agencies investigating this incident. Facts were compiled by examining evidence at the incident site, conducting interviews, and reviewing documentation. To minimize duplication of effort, the team used the information collected by other agency to the maximum extent practical.

The diagram illustrates a refinery configuration with the following components and flows:

- Inputs:** AR, LSR, H2 Rich Gas.
- Units:** VDU, U/C, Sulf Plant, V R D S, H2 Plant, PSA-2.
- Streams:**
  - AR splits into a feed for VDU and a bypass.
  - VDU outputs H/C VGO to U/C and VR to V R D S.
  - LSR feeds H2 Plant, which outputs H2 to V R D S.
  - H2 Rich Gas feeds PSA-2, which outputs H2 to V R D S.
  - U/C outputs C1 & C2, C3+C4 (via LSU/GCU), Lt Naph, Hw Naph, Kerosene, Diesel, and UCO.
  - Sulf Plant receives input from U/C and V R D S, and outputs ASPHALT (AS REQ'D) and SULF.
  - V R D S receives VR, H2, and UCO, and outputs U/NAPH, B/C, and UCU.
- Outputs:** FUEL (FOEBBL/D), C3, C4, L/N, H/N, KFR, DSL, ASPHALT (AS REQ'D), SULF, U/NAPH, B/C, UCU.






Fig.3 : UC Process Flow Diagram




Fig. 4 : Point of Incident of UC Unit

### 3.0 INCIDENT ANALYSIS

#### 3.1 Description

In the midnight of October, 2003 a pre-fractionator reboiler fired in a UC(Unicracking) Unit of HOU (Heavy Oil Upgrading)Plant, Ulsan, Korea. The fire broke out on the eighth row tube on the convection part of the heater. It continued for 2 hours and damaged reboiler itself and facilities. The upper side of the convection tube (pass 'E' ; row 8 in Pre-fractionator reboiler heater) had ruptured that it caused fire,



Fig. 5: Ruptured Tube




Fig. 6 : Heater Tube Arrangement



**Fig. 7 : Appearance of the Reboiler Heater after Fire**



**Fig. 8 : Ruptured Tube Detached from the Heater Convection Box**

## 4.0 Result of Investigation

### 4.1 Convection Tube Inspection Result

- Generally it has a kind of high temperature  $H_2S$ -  $H_2$  Corrosion trend and especially the corrosion of middle row is more serious than that of lower row tube walls in the convection section under high temperature. The rows 7 and 8 showed more serious corrosion.

### 4.2 Convection Tube Scaling Analysis Result

- In the view of external inspection and component analysis, most of contents were  $FeS$  which was corrosion residue of tube metal from typical Sulfur.




Fig. 9 : View of Scale in the Tube Inside -EDX(Energy Dispersive X-Ray)Analysis

### 4.3 Vapor/Liquid Pattern and Flow Regime Analysis inside Convection Tube

- Slug flow existed cause of vaporization in the convection tube, and this part was not much affected under real operation fluctuation range condition .
- In addition to rupture pass, other passes were also detected serious thin condition in 7,8 rows. From this result, the section of ventilation was supposed to be limited, therefore the cause of accident was not short term corrosion but long term one.
- 

### 4.4 Corrosion Mechanism

As flow temperature was going up in the convection tube, the vaporization was occurred, initial bubble type vapor components were crashed each other and after all converted into slug flow type flow regime. In the slug flow zone, high concentration  $H_2S$  vapor was driven to upper tube side, therefore  $H_2S$  concentration and tube metal temperature was getting higher and higher in this spot, as time goes by, high temperature  $H_2S$  -  $H_2$  corrosion broke out very seriously. This corrosion rates was very high, even if total sulfur content is low (several parts per million [ppm]).

## **5.0 ROOT CAUSE**

### **5.1 Tube rupture by high temperature H<sub>2</sub>S- H<sub>2</sub> Corrosion**

The general corrosion of whole tube and local corrosion of slug flow inside tube from material vaporization made the thickness of tube to be thin therefore it became of tube rupture.

## **6.0 RECOMMENDATIONS**

### **6.1 Material of Construction of Reboiler Heater Tube Upgrade**

Reboiler heater tube and subsidiary tube material of construction need to be upgraded. In addition, the scope of material selection and replacement policy shall be rechecked and revised.

### **6.2. Reassurance of Convection Heater Tube Inspection Period and Method**

Convection tube inspection period & inspection method shall be revised considering operation condition of heater convection section, material and corrosion status, and then the inspection period and method to be decided clearly.

## **7.0 REFERENCE**

National Association of Corrosion Engineers, *Overview of Sulfidic Corrosion in Petroleum Refining*; Proposed NACE Technical Committee Report: NACE International, Houston, Texas, 2003.